WINNER FOR FEB-2016:

BEST ZONE TROPHY: SJ 11 (CONSISTENT AT TOP WITH 93% SCORE)

BEST IMPROVED ZONE: IT (VERY GOOD ATTEMPT AND EFFORTS. VISIBLE CHANGE)





WINNER FOR FEB. : 2016



BEST ZONE: SJ-11

BEST IMPROVED ZONE : IT



We are The Chaimpions of 5S Best Improved Zone of Feb. 2016





Side wall of Mill to no. 1 to be glass fitted, for natural lighting & power saving.



Side wall of Mill to no. 1 to be glass fitted, for natural lighting & power saving.



SOP of operation of machines & main activities to be prepared and to be displayed in front of panel (4S)



Operators should be equipped with ear plugs for safety.




2S (Set Location) for empty buckets



2S (Set Location) for motors in motor winding room



2S (set locations) should be done in almirah



2S(shadow board) for keeping tools should be done in motor winding room



Proper 2S(High level address) with white color should be done in motor winding room



2S marking and sign boarding should be done in packing area.



2S marking and sign boarding should be done in packing area.



2S marking and sign boarding should be done in packing area.



2S marking, walkway marking and sign boarding should be done in packing area.